

National Transportation Safety Board
Washington, DC 20594

Printed on : 1/9/2011 8:10:56 PM

Brief of Accident

Adopted 02/26/2007

LAX05LA288 File No. 20981	09/03/2005	Trona, CA	Aircraft Reg No. N912TT	Time (Local): 08:30 PDT		
Make/Model:	Goodlett / Safari			Fatal	Serious	Minor/None
Engine Make/Model:	Lycoming / O-320-B2C		Crew	0	0	1
Aircraft Damage:	Substantial		Pass	0	0	0
Number of Engines:	1					
Operating Certificate(s):	None					
Type of Flight Operation:	Personal					
Reg. Flight Conducted Under:	Part 91: General Aviation					
Last Depart. Point: Ridgecrest, CA				Condition of Light: Day		
Destination: Local Flight				Weather Info Src: Weather Observation Facility		
Airport Proximity: Off Airport/Airstrip				Basic Weather: Visual Conditions		
				Lowest Ceiling: None		
				Visibility: 65.00 SM		
				Wind Dir/Speed: 360 / 004 Kts		
				Temperature (°C): 24		
				Precip/Obscuration: No Obscuration; No Precipitation		
Pilot-in-Command	Age: 44			Flight Time (Hours)		
Certificate(s)/Rating(s)				Total All Aircraft: 680		
Private; Single-engine Land; Helicopter				Last 90 Days: 12		
				Total Make/Model: 117		
Instrument Ratings				Total Instrument Time: UnK/Nr		
None						

The experimental helicopter impacted terrain after experiencing a failure of a flight control connecting rod. According to the pilot, he was maneuvering the helicopter about 50 feet above the ground when he heard a loud bang followed by a whirring or buzzing noise. The helicopter rolled to the left, which the pilot was unable to counter with control inputs, and impacted terrain on the left side. A post-accident examination of the helicopter by the pilot/builder revealed that a 27.875-inch aluminum control rod was fractured near the middle of the rod. The control rod was connected between the collective-cyclic mixing assembly and a walking beam that connected to the stationary swash plate of the left side (pilot side) of the helicopter. The break in the control rod was perpendicular to the longitudinal axis of the rod. Examination of the control rod by a metallurgical laboratory revealed the failure was a result of a fatigue crack that had propagated through nearly 75 percent of the control rod. A portion of the break was polished indicating that the crack had been present for quite some time. The pre-existing crack in the control rod reduced its strength to a point that allowed the flight control forces to fail the remaining material. According to the pilot/builder, a break in the control rod would result in flight characteristics consistent with that experienced by the pilot during the accident flight. The control system has been redesigned by the kit manufacturer as a result of this accident and now incorporates steel control rods as opposed to aluminum ones.

Brief of Accident (Continued)

LAX05LA288
File No. 20981 09/03/2005 Trona, CA Aircraft Reg No. N912TT Time (Local): 08:30 PDT

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: MANEUVERING

Findings

1. (C) ROTORCRAFT FLIGHT CONTROL,CYCLIC CONTROL ROD - FATIGUE
2. (C) ROTORCRAFT FLIGHT CONTROL,CYCLIC CONTROL ROD - FAILURE,TOTAL

Occurrence #2: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: MANEUVERING

Findings

3. AIRCRAFT CONTROL - NOT POSSIBLE - PILOT IN COMMAND

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Findings

4. TERRAIN CONDITION - GROUND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.
the in-flight fatigue failure of a control system connecting rod, which resulted in a loss of helicopter control.